Macroseismic Intensity Map USGS
ShakeMap: 9 km SE of Esmeraldas, Esmeraldas, EC
Mar 27, 2022 04:28:13 UTC M5.8 N0.91 W79.59 Depth: 26.5km ID:us7000gxlu



SHAKING	Not felt	Weak	Light	Moderate	Strong	Very strong	Severe	Violent	Extreme
DAMAGE	None	None	None	Very light	Light	Moderate	Moderate/heavy	Heavy	Very heavy
PGA(%g)	<0.0464	0.297	2.76	6.2	11.5	21.5	40.1	74.7	>139
PGV(cm/s)	<0.0215	0.135	1.41	4.65	9.64	20	41.4	85.8	>178
INTENSITY	I	II-III	IV	V	VI	VII	VIII	IX	X+

Scale based on Worden et al. (2012)
Version 4: Processed 2022-03-28T04:29:26Z

△ Seismic Instrument ○ Reported Intensity ★ Epicenter