

M 7.5, NEW BRITAIN REGION, PAPUA NEW GUINEA

Origin Time: Sun 2015-03-29 23:48:31 UTC (09:48:31 local)


Location: 4.73°S 152.56°E Depth: 41 km

FOR TSUNAMI INFORMATION, SEE: tsunami.gov


Created: 7 weeks, 0 days after earthquake

Estimated Fatalities

Green alert for shaking-related fatalities and economic losses. There is a low likelihood of casualties and damage.



Estimated Economic Losses




Estimated Population Exposed to Earthquake Shaking

ESTIMATED POPULATION EXPOSURE (k = x1000)	- -*	2k*	360k	155k	185k	12k	0	0	0	
ESTIMATED MODIFIED MERCALLI INTENSITY	I	II-III	IV	V	VI	VII	VIII	IX	X+	
PERCEIVED SHAKING	Not felt	Weak	Light	Moderate	Strong	Very Strong	Severe	Violent	Extreme	
POTENTIAL DAMAGE	Resistant Structures	none	none	none	V. Light	Light	Moderate	Moderate/Heavy	Heavy	V. Heavy
	Vulnerable Structures	none	none	none	Light	Moderate	Moderate/Heavy	Heavy	V. Heavy	V. Heavy

*Estimated exposure only includes population within the map area.

Population Exposure



Structures:

Overall, the population in this region resides in structures that are vulnerable to earthquake shaking, though some resistant structures exist. The predominant vulnerable building types are unreinforced brick masonry and informal (metal, timber, GI etc.) construction.

Historical Earthquakes (with MMI levels):

Date (UTC)	Dist. (km)	Mag.	Max MMI(#)	Shaking Deaths
2000-10-29	174	6.9	VII(41k)	0
1985-05-10	191	7.2	VII(28k)	1
1983-12-21	107	6.2	VII(5k)	10

Recent earthquakes in this area have caused secondary hazards such as tsunamis and landslides that might have contributed to losses.

Selected City Exposure

from GeoNames.org

MMI City	Population
VI Kokopo	26k
V Rabaul	8k
V Namatanai	1k
IV Kavieng	14k
IV Kimbe	19k
IV Panguna	3k
IV Arawa	40k

bold cities appear on map

(k = x1000)

PAGER content is automatically generated, and only considers losses due to structural damage. Limitations of input data, shaking estimates, and loss models may add uncertainty.

<http://earthquake.usgs.gov/pager>

Event ID: us10001rvu