Macroseismic Intensity Map USGS
ShakeMap: 68 km S of Punta de Burica, Chiriquí, PA
Jul 21, 2021 21:15:12 UTC M6.7 N7.42 W82.79 Depth: 10.0km ID:us6000exs5



SHAKING	Not felt	Weak	Light	Moderate	Strong	Very strong	Severe	Violent	Extreme
DAMAGE	None	None	None	Very light	Light	Moderate	Moderate/heavy	Heavy	Very heavy
PGA(%g)	<0.0464	0.297	2.76	6.2	11.5	21.5	40.1	74.7	>139
PGV(cm/s)	<0.0215	0.135	1.41	4.65	9.64	20	41.4	85.8	>178
INTENSITY	I	II-III	IV	V	VI	VII	VIII	IX	X+

Scale based on Worden et al. (2012) Version 5: Processed 2021-07-27T01:57:28Z

△ Seismic Instrument ○ Reported Intensity ★ Epicenter ▭ Rupture