
USGS

Operator: Tom Noce Sounding: 47 BZA011 Cone Used: DDG0770 CPT Date/Time: 1/6/2006 12:38:28 PM Location: Brazoria WR Autotour Turnaround Job Number: Qal



*Soil behavior type and SPT based on data from UBC-1983