


# US Geological Survey

Operator: Shaler/Bennett  
 Sounding: IMC138  
 Cone Used: old econe no #

CPT Date/Time: 03-03-84 08:00  
 Location: Northend dam NR1  
 Job Number: Fluvial



Maximum Depth = 10.60 meters

Depth Increment = 0.100 meters

- |                          |                             |                            |                                |
|--------------------------|-----------------------------|----------------------------|--------------------------------|
| 1 sensitive fine grained | 4 silty clay to clay        | 7 silty sand to sandy silt | 10 gravelly sand to sand       |
| 2 organic material       | 5 clayey silt to silty clay | 8 sand to silty sand       | 11 very stiff fine grained (*) |
| 3 clay                   | 6 sandy silt to clayey silt | 9 sand                     | 12 sand to clayey sand (*)     |

\*Soil behavior type and SPT based on data from UBC-1983