


US Geological Survey

Operator: Mike Bennett
 Sounding: IMC158
 Cone Used: electric no #

CPT Date/Time: 11-04-88 08:22
 Location: Elmore Ranch 3
 Job Number: liquef yes



Maximum Depth = 6.90 meters

Depth Increment = 0.100 meters

- | | | | |
|--------------------------|-----------------------------|----------------------------|--------------------------------|
| 1 sensitive fine grained | 4 silty clay to clay | 7 silty sand to sandy silt | 10 gravelly sand to sand |
| 2 organic material | 5 clayey silt to silty clay | 8 sand to silty sand | 11 very stiff fine grained (*) |
| 3 clay | 6 sandy silt to clayey silt | 9 sand | 12 sand to clayey sand (*) |

*Soil behavior type and SPT based on data from UBC-1983