


US Geological Survey

Operator: Bennett\Criley
 Sounding: SFO031
 Cone Used: 329

CPT Date/Time: 03-07-94 11:18
 Location: Treasrue Island7
 Job Number:



Maximum Depth = 9.30 meters

Depth Increment = 0.100 meters

- | | | | |
|--------------------------|-----------------------------|----------------------------|--------------------------------|
| 1 sensitive fine grained | 4 silty clay to clay | 7 silty sand to sandy silt | 10 gravelly sand to sand |
| 2 organic material | 5 clayey silt to silty clay | 8 sand to silty sand | 11 very stiff fine grained (*) |
| 3 clay | 6 sandy silt to clayey silt | 9 sand | 12 sand to clayey sand (*) |

*Soil behavior type and SPT based on data from UBC-1983